SAFEBASE CASE HISTORY

SafeBase[™] Wall Anchors Cold Spring Granite, Cold Spring, MN



August 2023


SafeBasements of Minnesota was contacted to design a wall straightening system for a 100' retaining wall near a loading dock at Cold Spring Granite in

Cold Spring, MN. The wall was tipping in towards the loading dock and a repair plan was needed to prevent it from tipping further as well as pull it back into place. To achieve this, SafeBasements created a set of plans involving 18 SafeBase wall anchors placed every 5 ½ feet along the span of the wall.

Before the installation process began, excavation was performed by third parties directly behind the retaining wall to assist with the straightening of the wall. Once



Retaining wall before & after wall anchors



Top: Pulling back wall Bottom: Installed earth plate

Top: Driving anchor rod Bottom: Installed wall anchors

installed, the anchors were tightened until the wall was pulled back into its original place. Thus, the SafeBase wall anchors not only successfully restored the wall back to its original place, but also provided a long-term solution to keep it there.

SafeBasements of MN 60335 US Highway 12 Litchfield, MN 55355 320-593-8729 www.safebasements.com





SafeBasements, Inc. 28272 Minnie Street Paynesville, MN 56362 1-888-963-6892 www.safebasementsinc.com